MEMORANDUM

TO:	Board of Directors, Massachusetts School Building Authority
	Massachusetts School Building Authority
FROM:	John K. McCarthy, Executive Director
DATE:	May 18, 2016
RE:	Recommendation for 2016 Accelerated Repair Program Invitations

Recommendation

That the Executive Director be authorized to invite each of the schools listed in Attachment A, attached hereto, into the Accelerated Repair Program (the "ARP") to collaborate with the Massachusetts School Building Authority (the "MSBA") to conduct a Feasibility Study, as described in 963 CMR 2.00 et seq. The purpose of each Feasibility Study shall be to better understand the problems identified by the district in the Statement of Interest submitted to the MSBA and to explore options to repair these problems.

That the Executive Director be authorized to do all acts, to execute and deliver any and all documents and agreements, and to expend all funds necessary or desirable, in connection with conducting said Feasibility Study for each of the schools listed in Attachment A.

Discussion

Following the receipt of 67 Statements of Interest ("SOIs") filed in 2016 for the ARP, the MSBA performed a review of the information provided by the districts based upon the non-qualifying conditions noted below and for conformance with the ARP. Based upon that review, 56 schools were recommended for staff study site visits.

	Accelerated Repair 110gram Conditions
Roof Age	System is less than 20 years of age
Window Age	System is less than 20 years of age
Boiler Age	System is less than 20 years of age
Proposed Project Cost	Proposed total project cost is projected as less than \$250,000
Outside Scope	SOI itself identifies construction beyond roofs, windows, or boilers
Excess Boiler	SOI itself identifies boiler construction, excluding heating fuel storage
Scope	and/or delivery, beyond the physical limits of the existing boiler room(s)
Future Project	District plans a future construction project for MSBA participation going
Future Project	beyond roofs, windows, and boilers for the school
Overcrowding	School is judged by the district to be over-crowded
Building Usage	Primary use of the building is for non-educational purposes
School SOI	Facility condition not identified in SOI remains unresolved from previous
History	MSBA review
District-Wide	District is reviewing deficiencies to further identify its needs and priorities
Review	and/or consider the facility for potential consolidation

Non-Qualifying Accelerated Repair Program Conditions*

*The italicized conditions were not described in the 2016 SOI Opening letter provided to all Superintendents.

The MSBA conducted staff study site visits at 56 schools from April 6, 2016 through April 27, 2016. After collecting additional information during and after the site visits, six schools were declined consideration for invitation as identified in Attachment B. Of the 50 schools remaining, the MSBA will be recommending that 43 schools be invited into the 2016 ARP at the May 25, 2016 Board of Directors meeting. The remaining seven schools will be potentially considered for recommendation at the July 20, 2016 Board of Directors meeting, following the receipt of additional information from the Districts for staff review. Staff presented this information at the May 4, 2016 Facilities Assessment Subcommittee Meeting.

Attached to this memorandum are three exhibits:

- Attachment A identifies the forty-three (43) schools recommended for invitation in the ARP at the May 25, 2016 Board of Directors meeting, as well as the recommended project scope.
- Attachment B identifies the seventeen (17) schools not recommended for invitation into the ARP (including the six facilities that received staff study site visits) as well as the reason(s) these schools are not being recommended for participation in the ARP.
- Attachment C identifies the seven (7) schools that will be potentially considered for participation in the ARP at the July 20, 2016 Board of Directors meeting.

Invitation to Accelerated Repair Program

District	School	Age of Existing Building	Grade	2015/2016 Enrollment	Existing Square Footage	Scope Requested by District	Invited Scope Recommendation	Declined Scope Recommendation	Reasons for Declined Invitation
Agawam	Roberta G. Doering School	1921	7-8	601	91,506	Boiler	Boiler		
Auburn	Pakachoag Elementary School	1926	K-2	253	26,500	Roof	Roof		
Boston	Boston Latin School	1978	7-12	2,439	336,545	Boiler	Boiler - Partial		
Boston	James F. Condon Elementary School	1975	PK-6	837	140,426	Boiler	Boiler		
Boston	John W. McCormack Middle School	1967	6-8	519	115,941	Roof	Roof		
Boston	Paul A. Dever Elementary School	1957	PK-5	498	75,892	Roof	Roof		
Boston	William E. Channing Elementary School	1960	PK-5	292	32,582	Boiler	Boiler		
Boxford	Spofford Pond Elementary School	1963	3-6	425	76,895	Roof Windows/ Doors	Roof Windows/ Doors		
Cambridge	Fletcher Maynard Academy	1991	PK-5	258	84,206	Roof	Roof		
Canton	Lt. Peter M. Hansen Elementary School	1968	K-5	477	64,490	Roof	Roof		
Carver	Carver Middle-High School	1956	6-12	834	165,842	Roof Windows/ Doors Boiler	Roof Windows/ Doors Boiler		
Chicopee	Patrick E. Bowe School	1924	PK-5	438	73,520	Windows/ Doors	Windows/ Doors		
Chicopee	Chicopee Academy at Selser School	1957	9-12	101	36,235	Roof	Roof		
Dartmouth	Dartmouth Middle School	1956	6-8	982	193,345	Roof	Roof		
Gloucester	Gloucester High School	1939	9-12	865	246,326	Roof	Roof		
Halifax	Halifax Elementary School	1960	K-6	545	89,000	Roof Windows/ Doors	Roof Windows/ Doors		

Invitation to Accelerated Repair Program

District	School	Age of Existing Building	Grade	2015/2016 Enrollment	Existing Square Footage	Scope Requested by District	Invited Scope Recommendation	Declined Scope Recommendation	Reasons for Declined Invitation
Lawrence	High School Learning Center	1899	9-12	687	285,000	Boiler	Boiler		
Marshfield	Furnace Brook Middle School	1959	6-8	1,031	159,000	Roof	Roof		
Mashpee	Quashnet Elementary School	1978	3-6	505	132,247	Windows/ Doors	Windows/ Doors		
New Bedford	John A. Parker Elementary School	1964	PK-5	293	53,669	Windows/ Doors Boiler	Windows/ Doors	Boiler	District Request
North Brookfield	North Brookfield Elementary School	1972	PK-6	334	83,000	Roof	Roof		
Northampton	Bridge Street School	1920	PK-5	297	60,500	Roof	Roof		
Northampton	Leeds Elementary School	1953	K-5	330	74,000	Roof	Roof		
Quincy	Atherton Hough Elementary School	1911	K-5	267	46,549	Boiler	Boiler - Partial		
Quincy	Beechwood Knoll Elementary School	1951	K-5	355	35,820	Boiler	Boiler		
Quincy	Merrymount Elementary School	1929	K-5	346	43,750	Boiler	Boiler		
Quincy	Wollaston Elementary School	1913	K-5	350	34,576	Boiler	Boiler - Partial		
Sharon	Heights Elementary School	1955	K-5	490	85,252	Roof	Roof		
Somerville	Winter Hill Community Innovation School	1975	PK-8	428	95,000	Roof Windows/ Doors	Roof Windows/ Doors		
Springfield	Alfred G. Zanetti Montessori Magnet School	1964	PK-8	423	51,219	Windows/ Doors	Windows/ Doors		
Springfield	Thomas M. Balliet School	1948	PK-5	289	56,182	Roof	Roof		
Springfield	Balliet Middle School	1926	6-8	53	21,786	Windows/ Doors	Windows/ Doors		

Invitation to Accelerated Repair Program

District	School	Age of Existing Building	Grade	2015/2016 Enrollment	Existing Square Footage	Scope Requested by District	Invited Scope Recommendation	Declined Scope Recommendation	Reasons for Declined Invitation
Springfield	Kensington International School	1909	K-5	364	49,406	Roof	Roof		
Springfield	M. Marcus Kiley Middle School	1963	6-8	697	169,500	Windows/ Doors	Windows/ Doors		
Springfield	Mary M. Lynch Elementary School	1961	K-5	253	36,669	Roof	Roof		
Swansea	Elizabeth S. Brown Elementary School	1956	3-5	307	38,180	Windows/ Doors	Windows/ Doors		
Topsfield	Proctor Elementary School	1932	4-6	270	56,144	Roof	Roof		
Topsfield	Steward Elementary School	1961	PK-3	373	58,126	Roof	Roof		
Wayland	Loker Elementary School	1957	K-5	263	48,214	Windows/ Doors	Windows/Doors		
Worcester	Belmont Street Community School	1970	PK-6	582	92,988	Windows/ Doors HVAC/ Boiler	Windows/Doors	Boiler	Boiler Age
Worcester	Chandler Elementary Community School	1977	K-6	501	37,621	Windows/ Doors HVAC/ Boiler	Windows/Doors Boiler		
Worcester	Gerald Creamer Center	1926	10-12	150	29,857	Windows/Doors HVAC/Boiler	Windows/Doors Boiler - Partial	Boiler - Partial	Boiler Age
Worcester	Wawecus Road School	1963	K-6	145	22,974	Windows/ Doors	Windows/Doors		

Not Recommended for Accelerated Repair Program

District	School	Age of Existing Building	Grade	2015/2016 Enrollment	Existing Square Footage	Scope Requested by District	Invited Scope Recommendation	Declined Scope Recommendation	Reasons for Declined Invitation
Boston	Jackson/Mann K-8 School	1975	PK-8	775	207,798	Roof		Roof	Outside Scope (Site visit conducted)
Boston	Urban Science Academy	1996	9-12	497	227,030	Roof		Roof	Outside Scope (Site visit conducted)
Hampshire Regional School District	New Hingham Regional Elementary School	1998	PK-6	155	32,865	Roof		Roof	Roof Age
Duxbury	Alden School	1949	3-5	711	160,000	Windows/ Doors		Windows/ Doors	Proposed Project Cost (Site visit conducted)
Holyoke	Kelly Full Service Community School	1975	K-8	568	86,302	Windows/ Doors		Windows/ Doors	District-Wide Review
Holyoke	Lt. Clayre P. Sullivan Elementary School	1960	K-8	550	112,000	Windows/ Doors		Windows/ Doors	District-Wide Review
Holyoke	Lt. Elmer J. McMahon Elementary School	1961	K-8	400	35,201	Windows/ Doors		Windows/ Doors	District-Wide Review
Holyoke	Maurice A. Donahue Elementary School	1972	PK-8	517	70,550	Windows/ Doors		Windows/ Doors	District-Wide Review
Holyoke	Morgan Full Service Community School	1963	PK-8	382	62,397	Windows/ Doors		Windows/ Doors	District-Wide Review
Holyoke	Peck-Lawrence Full Service Community School	1971	4-8	329	158,198	Windows/ Doors		Windows/ Doors	District-Wide Review
Lawrence	Arlington Middle School	1985	5-8	1,158	154,000	Boiler		Boiler	Outside Scope (Site visit conducted)
Marshfield	Martinson Elementary School	1964	PK-5	473	92,000	Roof		Roof	Roof Age
Mohawk Trail Regional School District	Mohawk Trail Regional High School and Middle School	1969	7-12	444	147,717	Windows/ Doors HVAC/ Boiler		Windows/ Doors HVAC/ Boiler	District-Wide Review
Mohawk Trail Regional School District	Sanderson Academy	1996	PK-6	149	37,000	Windows/ Doors HVAC/ Boiler		Windows/ Doors HVAC/ Boiler	District-Wide Review
Springfield	Arthur T. Talmadge School	1954	K-5	276	37,055	Windows/ Doors		Windows/ Doors	School SOI History (Site visit conducted)
Springfield	Hiram L. Dorman School	1932	K-5	359	34,309	Roof		Roof	Roof Age (Site visit conducted)

Attachment B

Not Recommended for Accelerated Repair Program

District	School	Age of Existing Building	Grade	2015/2016 Enrollment	Existing Square Footage	Scope Requested by District	Invited Scope Recommendation	Declined Scope Recommendation	Reasons for Declined Invitation
Whitman-Hanson Regional School District	John H. Duval, Jr. School	1953	K-5	516	78,059	Roof		Roof	Roof Age

Attachment C

Pending Completion of Review for Accelerated Repair Program

District	School	Age of Existing Building	Grade	2015/2016 Enrollment	Existing Square Footage	Scope Requested by District
Norfolk County Agricultural School District	Norfolk County Agricultural High School	1915/1966/ 1988/1970	9-12	524	78,741	Roof Windows/ Doors Boiler
North Middlesex	Hawthorne Brook Middle School	1979	5-8	504	99,688	Windows/ Doors
North Middlesex Regional School District	Squannacook Early Childhood Center	1989	РК	70	58,400	Roof
North Middlesex Regional School District	Varnum Brook Elementary School	1977	K-4	574	136,047	Roof Windows/ Doors
Quaboag Regional School District	Quaboag Middle High School	1968	9-12	396	170,542	Boiler
Quaboag Regional School District	Warren Elementary School	1991	PK-7	467	74,000	Windows/ Doors
Revere	Garfield Middle School	1989	6-8	1,312	204,884	Boiler